

# **BLADE MOTOR**

Use NSN 6105-01-502-9448 to order a new lifting motor for your mine clearing blade. This motor has been tested and approved for use as a replacement for the current motor, NSN 6105-01-277-0295. You'll get the new motor faster.

#### OE-254/GRC Mast Section NSN

Mast section, NSN 5985-01-072-8066, is now NSN 5985-01-324-3463. Many of you are still ordering under the old NSN and entering an advice code of 2F—"obsolete. but still required." Stop it! Your request will just be rejected. Use the new NSN and the mast sections will come your way.

#### PS 607

# M1-SERIES TANK CANNON CLEANING

If you're using the Azure Blue portable cannon cleaning kit. NSN 1025-01-407-6027, to clean the main gun tube on your M1-series tank—STOP! The high-pressure water used as part of the cleaning process will corrode the gun tube and reduce its life span. Water also gets into the main gun system, causing corrosion and damage to the breech mechanism, bore evacuator components, and firing

### TFF RADAR TEST SET

Units, hold on to your money! Don't buy an off-the-shelf Identification Friend or Foe radar test set directly from a manufacturer. The AMCOM TMDE folks will field the new IFF RTS, TS-4530/UPM, NSN 6625-01-483-7194, in Sep 04 as free issue test equipment. If you have questions about the test set, contact AMCOM's John Fields at DSN 987-2934. (256) 313-2934 or email

john.fields@redstone.army.mil

P A

1900

## ROWPU Hotline

If you have questions about the operation, maintenance and logistics support for the 600-GPH and 3,000-GPH reverse osmosis water purification units (ROWPUs), write to the ROWPU's Hotline e-mail address at:

WaterSystems-ROWPU@tacom.army.mil

# **UH-60** Engine Control Quadrant Update

The connector plug (P105 & P106), NSN 5935-01-108-4483, shown on the control box parts list on page 39 of PS 601 is incorrect. It should be NSN 5935-01-109-7541.

#### M1-SERIES TANK LRUS

Before storing or shipping line replaceable units (LRUs) from your M1-series tank, check to see if it has a shipping container. These specially designed containers prevent damage to expensive LRUs. A quick look at the parts manual is all it takes. Then order a container if the right one's not on hand.

## UH-60 External Fuel Tank Access Panel

Mechanics, Fig 122, Item 24 of TM 1-1520-237-23P-5, lists the wrong screws (NSN 5305-00-137-3043) to mount the external fuel tank access panel. The correct screw is NSN 5305-01-343-1185. Make a note until the TM is updated. 

#### FIBER OPTIC CABLE

Order 300 meters of CX-13295/G fiber optic cable with NSN 6020-01-220-5435. Order 1,000 meters with NSN 6020-01-208-

### **AVLB** Engine

Use NSN 2815-01-166-2051 to order a new engine and container for your AVLB. The NSN shown for Item 1 in Fig 1 of TM 5-5420-202-24P and TM 5-5420-226-24P is no longer available.

# UH-60 Cargo Hook Impulse Cartridge

Need an NSN for the Black Hawk cargo hook impulse cartridge? Order NSN 1377-01-211-7211. The current cartridge, NSN 1377-01-254-1683, is no longer available in the supply system.

#### BRADLEY TURRET JAMS

Clean up brass cartridges from the catchers and the floor at every opportunity. Bradley crewmen in Iraq have had several turrets jammed by loose brass. Not good when you're engaging the enemy!

# No Annual ACADA Wipe Test

Unlike the CAM/ICAM and M8A1 chemical alarm, the M22 ACADA does not need the annual wipe test to check for radiation leaks. The ACADA needs to be wipe tested only when the radioactive source module is removed from the source assembly. And that can be done only at depot. So do not turn your ACADA into support for a wipe test. It's

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

# Would You Stake Your Life # the Condition of Your Equipment?

For Sale by the Superintendent of Documents. U.S. Government Printing Office nternet: bookstore.gpo.gov Phone: toll free (866) 512-1800; DC area (202) 512-1800